



Certificate of Acceptance Electrical Reticulation in Subdivisions Constructed by Subdivider

Name of Subdivision	PARK LAKE ADARE STG 1 ADARE
Location	ADARE
Subdividers Name	PARK LAKE ADARE PTY LTD
Supply Agreement No.	S0107577

Part A - Construction Acceptance		
I, (please print full name)	Ken Covington	employed by ENERGEX
as (position title)	Contract Officer	have carried out a final inspection of the
above subdivision and have sighted the consultant's certification that the electrical installation has been carried out to the		
satisfaction of ENERGEX		
Signature		Date 31 01 2024

Part B - Material Reconciliation		
I, (please print full name)	THOMAS JEFFERIES	(position title) ASSESSMENT OFFICER
have carried out a reconciliation of material supplied to the above mentioned subdivision and am satisfied that the material		
supplied is in accordance with the estimate and all excess cable has been returned into Store		
Signature		Date 12/02/2024

Part C - Subdivision Supply Agreement Acceptance		
I, (please print full name)	THOMAS JEFFERIES	confirm that all requirements
relating to the supply agreement, including the registration of easements, have been met to the satisfaction of ENERGEX		
Signed for and on behalf of ENEREX by –		
Signature		Date 12/02/2024

Office Use Only		
Assets in terms of Agreement No.	transferred and vested in the name of ENERGEX	
Journal No.	Dated	/ /
Approved By (please print name)	Signature	

Certificate of Acceptance List

(To be completed by ENERGEX's Supervising Officer)

Description	Date	Initials
1 Commissioning Tests Reports received	/ /	
2 All excess cable returned	/ /	
3 All excess materials returned	/ /	
4 Recovered materials returned	/ /	
5 Developer paid for any additional materials not allowed for in the estimates	/ /	
6 Developer paid for any additional switching	/ /	
7 All civil works completed, eg E markers, retaining walls	/ /	
8 Labels fitted	/ /	
9 All conduits installed correctly	/ /	
10 Work quality to ENERGEX standard	/ /	
11 "As Constructed" drawings received	/ /	
12 Joint locations, etc specified on the drawings	/ /	
13 Road reserves, easements, transformer sites, registered with the Titles Office	/ /	
14 Street lights operating correctly	/ /	
15 Electricity supply pillars level	/ /	
16 Padmount transformer level	/ /	
17 No poles leaning	/ /	
18 Pole details received	/ /	
19 Test results received	/ /	