

## Certificate of Acceptance

### Electrical Reticulation in Subdivisions Constructed by Subdivider

<b>Name of Subdivision</b>	PARK LAKE ADARE Stage 4 & 5 ADARE
<b>Location</b>	ADARE
<b>Subdividers Name</b>	TTF PARK LAKE ADARE UNIT TRUST
<b>Supply Agreement No.</b>	S1302264

Part A - Construction Acceptance	
I, (please print full name)	Ken Covington
AS (position title)	Contact Officer
employed by ENERGEX	
have carried out a final inspection of the	
above subdivision and have sighted the consultant's certification that the electrical installation has been carried out to the	
satisfaction of ENERGEX	
<b>Signature</b>	<b>Date</b> 05/08 2025

Part B - Material Reconciliation	
I, (please print full name)	THOMAS JEFFERIES
	(position title) ASSESSMENT OFFICER
have carried out a reconciliation of material supplied to the above mentioned subdivision and am satisfied that the material	
supplied is in accordance with the estimate and all excess cable has been returned into Store	
<b>Signature</b>	<b>Date</b> / /

Part C - Subdivision Supply Agreement Acceptance	
I, (please print full name)	THOMAS JEFFERIES
	confirm that all requirements
relating to the supply agreement, including the registration of easements, have been met to the satisfaction of ENERGEX	
<b>Signed for and on behalf of ENERGEX by –</b>	
<b>Signature</b>	<b>Date</b> / /

Office Use Only	
Assets in terms of Agreement No.	transferred and vested in the name of ENERGEX
<b>Journal No.</b>	<b>Dated</b> / /
<b>Approved By</b> (please print name)	<b>Signature</b>

## Certificate of Acceptance List

(To be completed by ENERGEX's Supervising Officer)

Description	Date	Initials
1 Commissioning Tests Reports received	/ /	
2 All excess cable returned	/ /	
3 All excess materials returned	/ /	
4 Recovered materials returned	/ /	
5 Developer paid for any additional materials not allowed for in the estimates	/ /	
6 Developer paid for any additional switching	/ /	
7 All civil works completed, eg E markers, retaining walls	/ /	
8 Labels fitted	/ /	
9 All conduits installed correctly	/ /	
10 Work quality to ENERGEX standard	/ /	
11 "As Constructed" drawings received	/ /	
12 Joint locations, etc specified on the drawings	/ /	
13 Road reserves, easements, transformer sites, registered with the Titles Office	/ /	
14 Street lights operating correctly	/ /	
15 Electricity supply pillars level	/ /	
16 Padmount transformer level	/ /	
17 No poles leaning	/ /	
18 Pole details received	/ /	
19 Test results received	/ /	